### **Creative Arts 2**



Town of Barnstable ADA Transition Plan



200 Portland Street, Boston, MA 02114 www.IHCDesign.org • info@IHCDesign.org 617-695-1225 voice/ tty

#### **Background**

Year Built: 1830 Year Renovated: 2007-2009

Creative Arts 2 and Art Studio are located at 50 Pearl Street, Hyannis MA. Creative Arts 2 was originally a house, but it has been transformed into an art gallery space that displays work from local artists. A single-user toilet room located on the first floor is open to the public.

The site is split into three programs: a workshop with artwork that that is sold to the public, an indoor art gallery space, and artist studios. In addition, artwork is also displayed outside the building on a lawn of grass.

The parking lot by Creative Arts 2 is covered in the Town Hall parking narrative report and catalog.

IHCD team surveyed two buildings, the Creative Arts 2 and the Art Studio. The Creative Arts 2 building is two (2) stories, but only the first floor is open to the public. The art studio is a one (1) story building.

Creative Arts 2 has machinery that acts as a divider for members of the public who are viewing the workshop when it is in use. Some of the artwork can be purchased by the public, public access is limited to the viewing area, one (1) toilet room and the entrance.

A ramp is provided at the main entrance/egress door of the art gallery building. Inside there are 5 rooms that act as gallery spaces. Some rooms have been turned into art studios, however those rooms are closed to the public. One toilet room is open to the public. There are two (2) inaccessible egress doors, one is located on the west side of the building and the other on the north side.

### **Key Accessibility Issues**

#### **Exterior Accessible Routes**

Accessibility issues include lack of accessible routes to art studios, art exhibitions and wayside signs. In addition, there is an excessive change in level at the bottom of the ramp located at the main entrance/egress of the Creative Arts 2 building.

#### Single-User Toilet Room

Accessibility issues include lack of maneuvering clearance at the door. Toe and knee clearance is not provided at the lavatory, and the flush control is not on the open/transfer side. In addition, coat hooks are installed higher than the maximum allowed.

#### **Additional Accessibility Issues**

- · Lack of tactile signs at all egress doors.
- Directional signage is not provided at inaccessible egress doors directing people to the nearest accessible egress door.
- Lack of minimum door width at north side egress door.
- Operable parts are higher than the maximum allowed at the art studio.
- Wall cabinet protrudes into the circulation path.

### **Order of Magnitude Cost Estimates**

- Renovate and provide exterior accessible routes: \$4,576
- Renovate toilet room: \$5,270
- Renovate egress door (north side): \$2,232
- Provide an automatic door opener at the main entrance:
   \$3,060
- Miscellaneous corrective actions (signage, cane-detectable barriers, etc.): \$1,698

Total: \$16,836

ID	Location	Floor	Room El	lement	Туре	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
	Approach and Entrance											
	Exterior Access Route											
1	Entrance to Art Studio	Ext.	Ac	cterior ccess oute	Exterior	ArtStudio	ccessible route not provided	-	Ensure an accessible route is provided.  (Cost estimate of 4' wide and 6' long concrete path.)	1	384	\$384
2	Information Sign Near Parking Lot	Ext.	Ac	cterior ccess oute	Exterior	Ac	ccessible route not provided	-	Ensure an accessible route is provided to and around art exhibits.	1	576	\$576
3	Information Sign Near Creative Arts	Ext.	Ac	ccess oute	Exterior	Ac	ccessible route not provided	-	Ensure an accessible route is provided to the sign.  (Cost estimate of 4' wide and 15' long stone dust path.)	1	480	\$480
4	Exterior Art Installations by Creative Arts	Ext.	Ac	cterior ccess oute	Exterior	Ad	ccessible route not provided	-	Ensure an accessible route is provided to and around art exhibit.  (Cost estimate of 4' min. wide and 90' long stone dust path.)		2880	\$2880
	Exterior Ramp											
5	Main Entrance/Egr ess to Creative Arts	Ext.		tterior amp	N/A	Le	evel changes > 1/4"	1"	Alter change in level to be 1/4" high max.	1	256	\$256

ID	Location	Floor	Room	Element	Туре	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
	Entrance											
6	Main Entrance/ Egress at Creative Arts	Ext.		Entrance	Main Entrance		Maneuvering clearance is not provided	11"	Provide an automatic door opener. (18" min. pull side maneuvering clearance is required on the pull-side of the door.)	1	3060	\$3060
A	ccess to Good	ls and S	ervices									
	Means of Egr	ess										
7	Entrance/Egr ess at Art Studio	Ext.		Means of Egress	N/A		Tactile exit sign not provided	-	Ensure tactile exit signs with raised characters and braille are provided at exit doors. Mount signs between 48"- 60" above the finished floor located on the latch side of the door. If the exit sign is replaced with an illuminated exit sign, provide an illuminated International Symbol of Accessibility (ISA).	1	232	\$232
8	Main Entrance/ Egress at Creative Arts	1		Means of Egress	N/A		Tactile exit sign not provided	-	Ensure tactile exit signs with raised characters and braille are provided at exit doors. Mount signs between 48"- 60" above the finished floor located on the latch side of the door.	1	232	\$232
9	Creative Arts 2 Egress Door west Side	1		Means of Egress	N/A		Tactile exit sign not provided Directional sign to accessible emergency exit not provided	-	Provide a directional sign indicating the location of the nearest accessible emergency exit. Ensure tactile exit signs with raised characters and braille are provided at exit doors. Mount signs between 48"- 60" above the finished floor located on the latch side of the door.	1	464	\$464
10	Creative Arts 2 Egress Door north Side	1		Means of Egress	N/A		Tactile exit sign not provided Directional sign to accessible emergency exit not provided	-	Ensure tactile exit signs with raised characters and braille are provided at exit doors. Mount signs between 48"- 60" above the finished floor located on the latch side of the door.  Provide a directional sign indicating the location of the nearest accessible emergency exit.	1	464	\$464

Interior Acces				Photo	Issues	Current Measure	Recommendations (	Quantity	Price	Cost Estimation
Interior Access Route										
Creative Arts Room 3	1	Interior Access Route	N/A		Obstructed by protruding objects	11.5"	Provide a cane-detectable barrier at the wall cabinet.	1	306	\$306
Doors, Doorw	ays, & Gates									
Creative Arts 2 Emergency Exit on North Side	1	Doors, Doorways, & Gates	Emergency Egress		Clear width at door < 32"	29.5"	Widen the door so that there is 32" min. clear width.	1	2232	\$2232
Creative Arts 2 Single-User Toilet Room	1	Doors, Doorways, & Gates	Toilet Room		Maneuvering clearance(s) not provided	10"	Provide an automatic door opener. (18" min. pull side maneuvering clearance is required on the pull-side of the door.)	1	3060	\$3060
Operable Part	s									
Near Entrance to the Art Studio	Ext.	Operable Parts	Other		Reach < 15" or > 48"(forward/side approach)	64"	Relocate chains so that they are between 15"-48" above the finished floor.	1	Labor	\$0
	Creative Arts 2 Emergency Exit on North Side  Creative Arts 2 Single-User Toilet Room  Operable Part  Near Entrance to the Art Studio	2 Emergency Exit on North Side  Creative Arts 2 Single-User Toilet Room  Operable Parts  Near Entrance to	Creative Arts 2 Emergency Exit on North Side  Creative Arts 1 Doors, & Gates  Creative Arts 2 Single-User Toilet Room  Coperable Parts  Near Ext. Operable Parts  Near Entrance to the Art Studio	Creative Arts 2 Emergency Exit on North Side  Creative Arts 2 Single-User Toilet Room  Operable Parts  Near Entrance to the Art Studio  Creative Arts 1 Doors, Doorways, & Gates  Operable Parts  Operable Parts  Operable Parts  Operable Parts  Operable Parts  Operable Parts  Operable Parts	Creative Arts 2 Emergency Egress  Noorways, & Gates  Creative Arts 2 Single-User Toilet Room  Coperable Parts  Near Entrance to the Art Studio  Creative Arts 2 Doors, Doorways, & Gates  Operable Parts  Operable Parts  Operable Parts  Other Parts	Creative Arts 2 Emergency Exit on North Side  Creative Arts 2 Single-User Toilet Room  Coperable Parts  Ext. Operable Parts  Ext. Operable Parts  Creative Art Studio  Creative Arts 2 Single-User Toilet Room  Doors, Doorways, & Gates  Coperable Parts  Ext. Operable Parts  Creative Art Studio  Creative Arts 2 Single-User Toilet Room  Maneuvering clearance(s) not provided  Reach < 15" or > 48"(forward/side approach)	Creative Arts 2 Emergency Exit on North Side  Creative Arts 2 Single-User Toilet Room  Doors, Barts 2 Single-User Toilet Room  Doers, Barts 3 Side Side Side Side Side Side Side Side	Creative Arts 2 Emergency Ext on North Side  Creative Arts 3 Doors, 2 Emergency Ext on North Side  Creative Arts 4 Doors, 3 Gales	Creative Arts 2 Emergency Exit on North Side  Creative Arts 2 Emergency Exit on North Side  Creative Arts 1 Doors, 8 Gates  Creative Arts 2 Single-User Doorways, 9 Gates 2 Singl	Creative Arts 2 Emergency Exit on North Side  Creative Arts 2 Emergency Exit on North Side  Creative Arts 2 Single-User Toilet Room  Doorways, 8 Gates  Creative Arts 2 Single-User Toilet

ID	Location	Floor	Room Element	Туре	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
	Lavatory										
15	Creative Arts 2 Single-User Toilet Room	1	Lavatory	N/A	T	oe or knee clearances not provided	25"	Provide at least one lavatory with knee and toe clearance positioned for a forward approach.	1	1686	\$1686
	Single-User Toilet										
16	Creative Arts 2 Single-User Toilet Room	1	Single-User Toilet	N/A		lush control not on open side	-	Relocate the flush control to the open side.	1	374	\$374
17	Creative Arts 2 Single-User Toilet Room	1	Single-User Toilet	N/A	, H	look located > 48" high	63.5"	Locate hook no higher than 48" above the finished floor.	1	150	\$150