

CONSTRUCTION DETAIL					CONSTRUCTION DETAIL (CONTINUED)					
Element	Cd	Description			Element	Cd	Description			
Style	99	Vacant Land								
Model	00	Vacant or OBY								
Grade:										
Stories										
Exterior Wall 1										
Exterior Wall 2										
Roof Structure										
Roof Cover										
Interior Wall 1										
Interior Wall 2										
Interior Floor 1										
Interior Floor 2										
Heat Fuel										
Heat Type										
AC Type										
Bedrooms										
Full Baths										
Half Baths										
Extra Fixtures										
Total Rooms										
Bath Style										
Kitchen Style										
Occupancy										
Usrflid 105										
Accessory Apt										
Foundation Alt										
Rms Prts										
Bath Split										
					CONDO DATA					
Parcel Id				C	Owne		0.0			
					B		S			
Adjust Type	Code	Description		Factor%						
Condo Flr										
Condo Unit										
					COST / MARKET VALUATION					
Building Value New					0					
Year Built					0					
Effective Year Built					0					
Depreciation Code										
Remodel Rating										
Year Remodeled										
Depreciation %					0					
Functional Obsol					0					
External Obsol					0					
Trend Factor					1					
Condition										
Condition %					0					
Percent Good										
RCNLD					0					
Dep % Ovr										
Dep Ovr Comment										
Misc Imp Ovr										
Misc Imp Ovr Comment										
Cost to Cure Ovr										
Cost to Cure Ovr Comment										
OB - OUTBUILDING & YARD ITEMS(L) / XF - BUILDING EXTRA FEATURES(B)										
Code	Description	L/B	Units	Unit Price	Yr Blt	Cond. Cd	% Gd	Grade	Grade Adj.	Appr. Value
CAB1	Cabin-Minimal	L	432	66.10	1969		50	00	1.00	14,300
BUILDING SUB-AREA SUMMARY SECTION										
Code	Description	Living Area	Floor Area	Eff Area	Unit Cost	Undeprec Value				
Ttl Gross Liv / Lease Area		0	0	0		0				

No Sketch