

CONSTRUCTION DETAIL			CONSTRUCTION DETAIL (CONTINUED)		
Element	Cd	Description	Element	Cd	Description
Style	94	Outbuildings			
Model	00	Vacant or OBY			
Grade:					
Stories					
Exterior Wall 1					
Exterior Wall 2					
Roof Structure					
Roof Cover					
Interior Wall 1					
Interior Wall 2					
Interior Floor 1					
Interior Floor 2					
Heat Fuel					
Heat Type					
AC Type					
Bedrooms					
Full Baths					
Half Baths					
Extra Fixtures					
Total Rooms					
Bath Style					
Kitchen Style					
Occupancy					
Sewer Occupan					
Accessory Apt					
Foundation Alt					
Rms Prts					
Bath Split					
CONDO DATA					
Parcel Id		C	Ownr	0.0	
			B	S	
Adjust Type	Code	Description	Factor%		
Condo Flr					
Condo Unit					
COST / MARKET VALUATION					
Building Value New			0		
Year Built			0		
Effective Year Built			0		
Depreciation Code					
Remodel Rating					
Year Remodeled					
Depreciation %					
Functional Obsol			0		
External Obsol			0		
Trend Factor			1		
Condition					
Condition %			0		
Percent Good					
RCNLD			0		
Dep % Ovr					
Dep Ovr Comment					
Misc Imp Ovr					
Misc Imp Ovr Comment					
Cost to Cure Ovr					
Cost to Cure Ovr Comment					

No Sketch

OB - OUTBUILDING & YARD ITEMS(L) / XF - BUILDING EXTRA FEATURES(B)

Code	Description	L/B	Units	Unit Price	Yr Blt	Cond. Cd	% Gd	Grade	Grade Adj.	Appr. Value
PKKG	Gravel Pkg Lot	L	4,200	1.06	1994		50		0.00	2,200

BUILDING SUB-AREA SUMMARY SECTION

Code	Description	Living Area	Floor Area	Eff Area	Unit Cost	Undeprec Value
Ttl Gross Liv / Lease Area		0	0	0		0

